	Work for Property Loc		Dunles	2558 North 36th Street		
	Property is: Single Fam	nily X	Duplex	Other		
Date:	9/15/2010	<u>—</u>				
take no respo	onsibility for problems discovered a	after the inspe	ction date	The City of Milwaukee, the Redevelopment Authorit, or for omissions through error or oversight. The list ral Block Grant or HOME programs.		
Exterior	Condition Report					
Location	Required Work		_	Note/Comments		Cost
Site	Landscaping	[	Yes	Self Help	\$	
	Steps/Handrails	n/a	Yes X	Repairs	\$	300.00
	Service walks	n/a	Yes X	Repairs	\$	500.00
	Fencing	n/a X	Yes		\$	
	Parking	n/a X	Yes 🗌		\$	
	Retaining walls	n/a X	Yes 🗌		\$	
	Other	n/a	Yes		\$	
	Other	n/a	Yes 🗍		\$	
Garage	<u> </u>	, 57			•	
	Singles: repair		Yes		\$	
	Shingles: Roof over existing	n/a X	Yes		\$	
	Shingles:Tear off & re-roof	n/a	Yes X	Replace	\$	1,500.00
	Gutters/downspouts	n/a	Yes X	Install	\$	500.00
	Flashing	n/a X	Yes		\$	
	Eaves	n/a X	Yes 🗌		\$	
	Siding	n/a	Yes X	Replace	\$	2,000.00
	Doors	n/a	Yes X	Install	\$	
	Windows	n/a X	Yes 🗌		\$	000.00
	Slab	n/a X	Yes 🗍		\$	
	Paint	n/a X	Yes 🗍		\$	
	Electrical		Yes 🗍		\$	
	Other		Yes X	Repairs to Stud Wall	\$	150.00
Porches	Roof	n/a X	Yes		\$	
	Deck-upper	n/a X	Yes 🗌		\$	
	Decklower	n/a X	Yes 🗍		\$	
	Steps/handrails		Yes X	Repairs	\$	300.00
	Ceiling		Yes	•	\$	
	Guardrails	n/a X	Yes 🗌		\$	
	Structural	n/a X	Yes		\$	
	Paint	n/a 🗓			\$	

n/a Yes

Other

\$

## House

Chimney	n/a Yes X <b>Repairs</b>	\$ 400.00
Shingles: repair	n/a X Yes	\$
Shingles: Roof over existing	n/a X Yes	\$
Shingles:Tear off & re-roof	n/a X Yes	\$
Gutters/downspouts	n/a Yes X Replace	\$ 700.00
Flashing	n/a X Yes	\$
Eaves	n/a X Yes	\$
Siding	n/a Yes X <b>Repairs</b>	\$ 300.00
Storm Doors	n/a X Yes	\$
Prime ("main") Doors	n/a X Yes	\$
Storm Windows	n/a X Yes	\$
Prime ("main") Windows	n/a X Yes	\$
Paint	n/a Yes X <b>Trim</b>	\$ 600.00
Foundation	n/a Yes X Brick Repairs	\$ 1,200.00
Electrical	n/a X Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$

Exterior: Estimated Cost:\*

9,050.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	, ,	X			Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work				Other	
<b>g</b>	Repair/replace boiler	n/a X	Yes			\$ 
	Repair radiation	n/a X	Yes			\$ 
	Repair/replace furnace	n/a X	Yes			\$ 
	Repair ductwork	n/a X	Yes			\$
	Replace thermostat	n/a X	Yes			\$
	Repair/replace grilles	n/a X	Yes			\$
Electrical	Tune boiler/furn. insp ht exchang	j∉n/a	Yes	Χ	Service Furnace	\$ 200.00
Licotriodi	Repair/replace receptacles	n/a X	Yes			\$
	Repair/replace switches	n/a X	Yes			\$
	Repair/replace fixtures	n/a X	Yes			\$
	Install outlets and circuits	n/a X	Yes			\$
	Install outlets and circuits	n/a X	Yes			\$
	Install outlets and circuits	n/a X	Yes			\$
	Install outlets and circuits	n/a X	Yes			\$
	Upgrade service	n/a X	Yes			\$
	Other	n/a	Yes			\$
	Other	n/a	Yes			\$
Plumbing	Repair/replace kitchen sink	n/a X	Yes			\$
	Repair/replace kitchen sink fauce	ein/a X	Yes			\$
	Repair/replace tub	n/a X	Yes			\$
	Repair/replace tub faucet	n/a X	Yes			\$
	Repair/replace toilet	n/a X	Yes			\$
	Repair/replace lavatory	n/a X	Yes			\$
	Repair/replace lavatory faucet	n/a X	Yes			\$
	Repair/replace wash tub	n/a X	Yes			\$
	Repair/replace wash tub faucet	n/a X	Yes			\$
	Unclog piping:	n/a X	Yes			\$
	Repair drain/waste/vent piping	n/a	Yes	X	Repair Drain Piping in Basement Floor	\$ 2,000.00
	Repair water piping	n/a X	Yes			\$
	Repair/replace water heater	n/a X	Yes			\$ 
	Other	n/a	Yes			\$ 
	Other	n/a	Yes			\$

Windows						
	Replace broken glass	n/a χ Y	es		\$	
	Repair or replace sash	n/a χ Y	es 🗌		\$	
Doors						
	Repair or replace doors	n/a χ Y	es		\$	
	Repair or repl. locks/latches	n/a χ Y	es 🗌	Self Help	\$	
Walls/Ceilin	gs					
	Repair or repl. @ defective	n/a Y	es X	Repairs	\$	500.00
Paint						
	Repair or repl. @ defective	n/a Y	es X	Complete Unit	\$	800.00
Fire Safety						
	Install smoke alarm:bsmt.	n/a X Y	es 🗍	Self Help	\$	
	Install smoke alarm: 1st flr.	n/a X Y	es	Self Help	\$	
	Install smoke alarm: 2nd flr.	n/a X Y	es 🗌	Self Help	\$	
Handrails						
Ctaira	Repair/replace defective	n/a Y	es X	Self Help Upper Rail	\$	50.00
Stairs	Repair defective	n/a Y	es X	Repairs to Upper & Lower	\$	600.00
Floors			_			
Other	Repair defective	n/a  χ   Y	es		\$	
		n/a Y	es 🗌		\$	
		n/a Y	es 🗌		\$	
		n/a Y	es 🗌		\$	
		n/a Y	es 🗌		\$	
				Interior: Estimated Cost:	\$	4,150.00
				Total Exterior and Interior Cost:*	\$	13,200.00
					<u> </u>	-,

Prepared by: S. Denny / Inspected by: Paul Geboy Date: 9/16/10

## **Self Help**

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.